T-75 Moore Farmhouse nr. Queen Anne site private

The James F. Moore Farmhouse was demolished after the photo was taken in 1970. Nothing remains on the site above ground.

## INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

T NAME OF THE PARTY OF THE PART					
1 NAME					
HISTORIC					
AND/OR COMMON					
	omo Hougo				
James F. Mo			· · · · · · · · · · · · · · · · · · ·		
2 LOCATION					
STREET & NUMBER					
Blade Rd.,	.6 mile west of Mo	1. Rt. 309			
CITY, TOWN			CONGRESSIONAL DISTRICT		
Queen Anne	VICINITY OF		First		
state Maryland				COUNTY Talbot	
3 CLASSIFIC	ATION				
CATEGORY	OWNERSHIP	STATUS		SENT USE	
DISTRICT BUILDING(S)	PUBLIC PRIVATE	_OCCUPIED  ∠UNOCCUPIED	∠AGRICULTURE	MUSEUM	
STRUCTURE	∠PRIVATEBOTH		COMMERCIAL	PARK	
±SITE	PUBLIC ACQUISITION	WORK IN PROGRESS ACCESSIBLE	EDUCATIONALENTERTAINMENT	PRIVATE RESIDENCERELIGIOUS	
OBJECT	IN PROCESS	_YES: RESTRICTED	GOVERNMENT	SCIENTIFIC	
	BEING CONSIDERED	YES: UNRESTRICTED	INDUSTRIAL	TRANSPORTATION	
		NO	MILITARY	OTHER:	
4 OWNER OF James F. Mo			Telephone #:		
street & NUMBER 96 Stauffer	· Road				
CITY, TOWN			STATE ,	zip code	
Severna Par	<u> </u>	VICINITY OF	Maryland 21	.146	
5 LOCATION	OF LEGAL DESCR	IPTION	Tibor # 100		
			Liber #: 498		
COURTHOUSE. REGISTRY OF DEEDS,E	ETC. Talbot County Co		Folio #: 600		
STREET & NUMBER	Taibor County Co	our thouse			
Washington	Street				
CITY, TOWN		· · · · · · · · · · · · · · · · · · ·	STATE	<u> </u>	
Easton	Easton		Maryland 216	501	
6 REPRESEN	TATION IN EXIST	ING SURVEYS			
TITLE					
DATE		FEDERAL	STATECOUNTYLOCA	1	
DEPOSITORY FOR					
SURVEY RECORDS			CTATE		
CITY, TOWN			STATE		
				<del></del>	



CONDITION

CHECK ONE

CHECK ONE

\_\_EXCELLENT

\_\_DETERIORATED

\_\_UNALTERED

YORIGINAL SITE

\_\_GOOD \_\_FAIR

\_RUINS

ZUNEXPOSED

ALTERED

\_\_MOVED DATE\_\_\_\_\_

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The James F. Moore Farmhouse was demolished after the photo was taken in 1970. Nothing remains on the site above ground.

	COMMERCE	ENGINEERING EXPLORATION/SETTLEMENT	MUSIC PHILOSOPHY	THEATERTRANSPORTATION
	ARCHITECTURE	EDUCATION	MILITARY	_SOCIAL/HUMANITARIAN
_1400-1499	ARCHEULUGY-PREHISTORIC ARCHEOLOGY-HISTORIC AGRICULTURE	—COMMUNITY PLANNING —CONSERVATION —ECONOMICS	LANDSCAPE ARCHITECTURELAWLITERATURE	RELIGIONSCIENCESCULPTURE

## STATEMENT OF SIGNIFICANCE

The Moore farm was included in the survey of sites in 1970 due to its form, which follows the lines of those buildings constructed throughout the 18th and first half of the 19th centuries. Although the two story portion appeared late, early 20th century, the rear one and one-half story wing seemed earlier, and may indeed have been the original house or part of an earlier house.

As it stood in 1970, it was composed of two rooms on both floors with a single window and door to each room on the east side. Two dormers pierced the roof as did a central chimney. Typical of the early 19th century, especially noticeable in Caroline County, was the fact that the 4/4 sash in the dormers were set horizontally.

## 9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSA	RY
10 GEOGRAPHICAL DATA  ACREAGE OF NOMINATED PROPERTY	
VERBAL BOUNDARY DESCRIPTION	
LIST ALL STATES AND COUNTIES FOR PROPERTIES OV	ERLAPPING STATE OR COUNTY BOUNDARIES
STATE CO	UNTY
STATE CO	UNTY
11 FORM PREPARED BY NAME / TITLE	tont
Michael Bourne, Architectural Consul	DATE
Maryland Historical Trust	January, 1977
STREET & NUMBER	TELEPHONE
Shaw House, 21 State Circle	STATE
CITY OR TOWN	Maryland 21401
Annapolis	1102 / 2011

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust

The Shaw House, 21 State Circle

Annapolis, Maryland 21401

(301) 267-1438



11 X1.70

75%

75

12/70 MiBourne East facade

James F. Moore House

T-75